


# **COAX PATCH PANELS**

Manual transfer patch panel assembly, 3 pole, one (1) 180° connector, includes 3 anchor connectors and 3 line clamps. Screwdriver mounted on panel. Not pressurized.

# Catalog no.

31103 - 1 <sup>5</sup> / <sub>8</sub> "	31104 - 3 <sup>1</sup> / <sub>8</sub> "
31102 - 4 <sup>1</sup> / <sub>16</sub> "	31105 – 6 <sup>1</sup> / <sub>8</sub> "

(3 <sup>1</sup>/<sub>8</sub>" Panel Illustrated)




Manual transfer 4 pole patch panel assembly with (2) 180° elbows, includes 4 anchor connectors and 4 line clamps. Screwdriver mounted on panel. Not pressurized.

## Catalog no.

31403 - 1 <sup>5</sup> / <sub>8</sub> "	$31404 - 3^{1}/8$ "
31402 - 4 <sup>1</sup> / <sub>16</sub> "	31405 - 6 <sup>1</sup> / <sub>8</sub> "

(3 <sup>1</sup>/<sub>8</sub>" Panel Illustrated)




Manual transfer 5 pole patch panel assembly with (2) 180° elbows, includes 5 anchor connectors and 5 line clamps. Screwdriver mounted on panel. Not pressurized.

### Catalog no.

31503 - 1 <sup>5</sup> / <sub>8</sub> "	31504 - 3 <sup>1</sup> / <sub>8</sub> "
$31502 - 4^{1/46}$	31505 - 6 <sup>1</sup> / <sub>6</sub> "

(3 <sup>1</sup>/<sub>8</sub>" Panel Illustrated)




Manual transfer patch panel assembly 7 pole, three (3) 180° connectors, includes 7 anchor connectors and 7 line clamps. Screwdriver mounted on panel. Not pressurized.

### Catalog no.

31703 - 1 <sup>5</sup> / <sub>8</sub> "	31704 - 3 <sup>1</sup> / <sub>8</sub> "
$31702 - 4^{1/46}$ "	31705 - 6 <sup>1</sup> / <sub>6</sub> "

(3 <sup>1</sup>/<sub>8</sub>" Panel Illustrated)





Interlocks are available for all sizes
All specifications are subject to change without notice